


Softwares:

1. Tcptools

2. MiniOS 7




01 02 00 00 00 06 00 06 00 70 00 80


Palert up counting mode  
For firmware update using

Softwares:

1. Tcptools

2. MiniOS 7





MiniOS7 Utility Version 3.2.6

File Connection Command Configuration Tools Help

Look in: MiniOS7\_Utility

Name	Size	Type	Modified	Attributes
bin		File Folder	2017/10/30 下午 02:...	
FIRMWARE		File Folder	2017/10/30 下午 02:...	
OS_IMAGE		File Folder	2017/10/30 下午 02:...	
icpdas	1KB	URL File	2017/10/30 下午 02:...	A
load232.dll	88KB	DLL File	2007/1/31 下午 12:52	A
MiniOS7_Utility	1,015KB	CHM File	2009/10/15 上午 09:...	A
MiniOS7_Utility	2,544KB	EXE File	2014/1/20 上午 10:07	A
MiniOS7_Utility	1KB	INI File	2018/1/15 下午 02:53	A
MiniOS7_Utility	896KB	RAR File	2017/12/22 下午 05:...	A
uart.dll	56KB	DLL File	2006/12/8 上午 10:07	A
unins000	10KB	DAT File	2017/10/30 下午 02:...	A
unins000	675KB	EXE File	2017/10/30 下午 02:...	A

Look in: Disk A 111,714 bytes available

No	Name	Size	Modified
0	autoexec.bat	10	2012/3/14 上午 09:05:04
1	pl00	84,788	2017/7/21 下午 06:10:04

Run  
Run with parameters...  
Reset MiniOS F4  
Erase Disk

uPAC-7186EX\_UDP>IP:192.168.255.1 Port:23 via UDP, 2 file(s) 84,798 bytes

Connection(F2) Upload(F5) DiskTool(F6) Info(F7) Delete(F8) Refresh(F9) Console(F10) DOS(F11) Search(F12)

上午 11:14  
2018/1/16

MiniOS7 Utility Version 3.2.6

File Connection Command Configuration Tools Help

Look in: latestfirmware

Lock in: Disk A 111,714 bytes available

Name	Size	Type	Modified	Attributes
7188eu	1KB	INI File	2018/1/15 下午 02:49	A
autoexec	1KB	BAT File	2012/3/14 上午 09:05	A
pl00143	82KB	EXE File	2017/7/21 下午 06:10	A

No	Name	Size	Modified
0	autoexec.bat	10	2012/3/14 上午 09:05:04
1	pl00143.exe	84,788	2017/7/21 下午 06:10:04

uPAC-7186EX\_UDP>IP:192.168.255.1 Port:23 via UDP, 2 file(s) 84,798 bytes

Connection(F2) Upload(F5) DiskTool(F6) Info(F7) Delete(F8) Refresh(F9) Console(F10) DOS(F11) Search(F12)

上午 11:16 2018/1/16

